## **Capital Development Committee**




**Colorado Department of Corrections** 

Presentation & Testimony December 2023





### **Overview**







**Colorado Department of Corrections** 

@ 2022 Mapbox @ OpenStreetMap



602 State Owned Buildings (6,845,605 SF)

- CCi Facilities
- 25 Leased Spaces (307,512 SF)
  - 19 Community Parole Offices
    - one is in a State building
  - Training Academy
  - Headquarters Offices
  - CMHI-P IGA's
  - CCi Surplus
- •Total 7,153,117 SqFt




Colorado Territorial Correctional Facility
Security Tower






- Buildings
  - 31% over 50 years of age
  - 73% over 25 years of age
  - Range from 1871 to 2010
  - 47% infrastructure over 50 years of age
- Five Year Plans
  - CC & CR \$1,269,845,747 | 43 projects
  - CM \$95,714,156 | 44 projects
- Additional CC, CR & CM Projects
  - \$593,655,037 | 78 projects
     Not identified in five year plans
  - Does not include deferred maintenance below \$500k













Sterling Correctional Facility Steam condensate leaks damaged exterior soffit





Denver Women's Correctional Facility Outdated Door Security Controls



Trinidad Correctional Facility Blistered roof membrane







Buena Vista Correctional Facility Broken water line excavation



Arkansas Valley Correctional Facility Temporary water line patches




# **Submitted Projects**



- Capital Construction | Capital Renewal
  - \$220,201,676 15 projects
- Controlled Maintenance Projects
  - \$8,487,691 6 projects
- Project Impacts
  - Loss of Use
  - Life Safety | Security Impacts
  - Prolonged deferred maintenance typically results in system failure
  - 24/7/365 building use
- Goals
  - Maintain facility operations
  - Protect & maintain State assets
  - Reduction of maintenance & utility costs







# SCF Access Controls Electronic Security System Replacement OSPB Priority 3 | CDOC Priority 1



#### Capital Renewal Request—

- 2<sup>nd</sup> submission FY24|25
- \$40,029,390 Phase 2 of 2
- Previously funded Phase 1 of 2 \$9,396,252
- 2,584 male offenders Level V Facility
- Opened 1998

#### Issues –


- Failing door access control system
- Unavailability of replacement components
- System failure is a security & life safety risk

#### Funding Provides –

- Restores performance of this mission critical system
- Eliminate further system damage
- Restores staff confidence

#### Consequences –

- Complicated & compromised security operations
- Jeopardize staff, offender & public safety
- Continued deterioration of security systems



Sterling Correctional Facility Security Control Center




# SCF Access Controls Electronic Security System Replacement OSPB Priority 3 | CDOC Priority 1





Sterling Correctional Facility Manual key controls



Sterling Correctional Facility
Interim pneumatic controls




# SCF Steam Condensate Line Replacement OSPB Priority 7 | CDOC Priority 2



- Capital Renewal Request—
  - FY 21|22 first submission
  - \$24,854,531 Phase 2
  - Previously funded Phase 1 \$16,367,035
  - 2,584 male offenders Level V Facility
  - Opened 1998
- Issues
  - Failing steam heating system
  - Leaks repair often takes six weeks
  - System failure is a security & life safety risk
- Funding Provides
  - Restores performance of this mission critical system
  - Reduce loss of Facility use
  - Reduce litigation risk
- Consequences
  - Complicated & compromised operations
  - Loss of Facility use
  - Continued deterioration of heating & hot water system








# SCF Steam Condensate Line

Replacement

OSPB Priority 7 | CDOC Priority 2



Sterling Correctional Facility New vaults for system isolation



Sterling Correctional Facility Excavation of 12' to 20' depth for repairs





# CSP Electronic Security System Replacement



#### OSPB Priority 22 | CDOC Priority 3

#### Capital Renewal Request—

- FY 20|21 first submission
- **\$8,377,679**
- 756 male offenders Level V Facility
- Opened 1993 with an addition in 1998

#### Issues –

- Failing door control system faults, failures & outages
- Unavailability of replacement components
- System failure is a security & life safety risk

#### Funding Provides –

- Restores performance of this mission critical system
- Eliminate further system damage
- Restores staff confidence & eliminates temporary repairs

#### Consequences –

- Complicated & compromised security operations
- Jeopardize staff, offender & public safety
- Continued deterioration of security systems




Colorado State Penitentiary Key control operations



# CSP Electronic Security System Replacement OSPB Priority 22 | CDOC Priority 3










Colorado State Penitentiary Antiquated control panel






- DCC Generator & Controls
  - OSPB 16 | CDOC Priority 14
  - FY24|25 first submission as CR
  - **\$2,592,205**
  - 488 male Level I Facility
  - Opened 1964
- BVCF Critical Security Improvements -
  - OSPB 17 | CDOC Priority 8
  - FY24|25 2<sup>nd</sup> submission as Capital Renewal previously 4 phase CM
  - **\$5,894,431**
  - 1,234 male Level III Facility
  - Opened 1892
- FCF ADA Improvements
  - OSPB 18 | CDOC Priority 10
  - FY24|25 3<sup>rd</sup> submission as Capital Renewal previously 5 phase CM
  - **\$16,244,464**
  - 1,683 male Level III Facility
  - Opened 1957









**OSPB Un-Prioritized Projects** 





Buena Vista Correctional Facility Open cell fronts



Fremont Correctional Facility
Non-accessible shower




#### **OSPB Un-Prioritized Projects**



- DRDC Door Control Improvements -
  - OSPB 19 | CDOC Priority 9
  - FY23|24 1st submission as a CR
  - **\$2,180,248**
  - 638 male Level V Facility
  - Opened 1991
- AVCF Electronic Security Improvements
  - OSPB 21 | CDOC Priority 6
  - FY24|25 1st submission new scope
  - **\$23,548,071**
  - 1,105 male Level III Facility
  - Opened 1987
- ECCPC Electrical Distribution Infrastructure Replacement –
  - OSPB 23 | CDOC Priority 13
  - FY21|22 1st submission
  - **\$25,735,556**
  - Serves 6 correctional facilities plus CCi
  - 5,400 acres with 244 buildings















Arkansas Valley Correctional Facility Electrical door controls conditions





- DWCF Support Building Roof Replacement
  - OSPB 24 | CDOC Priority 11
  - FY24|25 5th submission as a Capital Renewal previously 1 phase CM
  - **\$3,710,858**
  - 1,016 female offenders Level V Facility
  - Opened 1998
- FCF Primary & Secondary Electrical Replacement
  - OSPB 26 | CDOC Priority 4
  - FY24|25 2<sup>nd</sup> submission
  - **\$35,606,931**
  - 1,683 male Level III Facility
  - Opened 1957
- FCF Fire Alarm Improvements
  - OSPB 28 | CDOC Priority 7
  - FY24|25 1st submission
  - **\$13,612,632**
  - 1,683 male Level III Facility
  - Opened 1957



Denver Women's Correctional Facility
Roof conditions











Fremont Correctional Facility Fire alarml distribution conditions





- LCF Support Roof Replacement -
  - OSPB 30 | CDOC Priority 12
  - FY24|25 1st submission
  - **\$4,493,603**
  - 1,234 male Level III Facility
  - Opened 1991
- TCF Waste Water Treatment Facility Improvements
  - OSPB 31 | CDOC Priority 5
  - FY24|25 1st submission
  - **\$18,941,389**
  - 508 male Level II Facility
  - Opened 1997
- BVCF Vocational Roof Improvements
  - OSPB 37 | CDOC Priority 15
  - FY24|25 1st submission
  - **\$2,866,,204**
  - 1,683 male Level III Facility
  - Opened 1889














Trinidad Correctional Facility WWTF treatment pond conditions

Buena Vista Correctional Facility Failed roof conditions





## Summary



- Department of Corrections
  - Largest Agency Building Inventory
  - Oldest Buildings
  - Aging infrastructure
  - 24/7/365 Operations & Building Use
  - Safety of inmates, staff & public
  - Defend in place facilities
- Project Impacts -
  - Avoid Loss of Use
  - Increase low OSA & DoRM Facility Condition Index (FCI)
  - Maintenance is critical
  - Prolonged deferred maintenance typically results in system failure
- Goals
  - Sustain facility operations
  - Protect & maintain State assets
  - Reduce maintenance & utility costs



Sterling Correctional Facility Steam condensate pipe conditions



# Questions & Final Remarks



